

# SOLID command

2358 GstarCAD MY /KW August 23, 2021 [CAD Commands](#) 0 1180

The **SOLID** command is used to create solid filled by triangles and quadrangles.

## Command Access:

**Command** : SOLID

## Command Prompts:

Specify first point:

Specify second point:

Specify third point:

Specify fourth point or :

Specify a point on desired side or [keep Both sides] :

## Function Description:

The selected 2D solid must be orthogonal with the observation direction and the FILLMODE system variable must be specified to 1, otherwise the solid could not be hatched.

## Relative Glossary:

### First point:

Specify the first point in the 2D solid.

### Second point:


Specify the first edge in the 2D solid.

### Third point:

Set the corner point relative to the second point.


### Fourth point or <exit>:

Set the fourth point relative to the first point. Press ENTER under the command prompt of "specify fourth point or ", it will create a filled triangle.



Users could continue to specify "the third point" and "the fourth point" to create more triangles and

quadrangles.



Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2358>