

VPMAX command

2430 GstarCAD MY /KW August 25, 2021 [CAD Commands](#) 0 1036

The **VPMAX** command is used to maximize the current viewport for editing.

Command Access:

Command : VPMAX

Shortcut : right-click and select "Maximize Viewport"

Command Prompts:

Select a viewport to maximize:
success Regenerating model.

Function Description:

Under this command, the viewport will cover the whole screen and switch to model space for conveniently editing.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2430>