

CONVTOMESH command

2046 GstarCAD MY /KW August 9, 2021 [CAD Commands](#) 0 1268

The **CONVTOMESH** command to convert eligible 3D objects into meshes, the objects will be smoothed at the same time in the conversion as well.

Eligible objects include : solids, closed polylines, regions, 3D face, 3D surfaces, polygon meshes.

FACETERMESHTYPE : System Variable, controls the level of smoothness upon conversion (If the mesh type is not set to be optimized, the converted object is not smoothed).

DELOBJ : System Variable, when sets the value to 0, the defining objects won't be deleted, when the value is -3, there will be a two options for users to choose delete or not, when it is 3, the defining objects will be deleted.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2046>