

Overview of Layers

2473 GstarCAD MY /KW April 15, 2022 [Workflow](#) 0 1303

As the main organizational tool for drawings, [LAYER](#) can be used to group information by function and to enforce [LINETYPE](#) , [COLOR](#) and other standards.

The following settings can be controlled: the default color, default linetype and lineweight ([LWEIGHT](#)), visibility and brightness, modify and display objects with different layer properties in individual layout viewports.

You start each new drawing with a layer named 0. This layer 0 cannot be deleted or renamed for the following reasons:

- Every drawing has at least one layer
- It is a special layer that relates to controlling colors in blocks

Related tutorial video:

- [Overview of layer](#) 00:20
- [Line command](#) 00:37
- [Draw Lines](#) 00:37
- [Properties command](#) 00:54
- [Propertiesclose command](#) 00:54
- [LAYISO command](#) 01:10
- [LAYUNISO command](#) 01:16
- [LAYER command](#) 01:20
- [Change layer settings and layer properties](#) 01:21
- [LAYMCUR command](#) 02:04
- [LAYDEL command](#) 02:48

Above video sources from [TUTORIAL - GETTING STARTED WITH GSTARCAD](#), enrol now for free.

Online URL: <https://www.kb2.gstarcad.com.my/article.php?id=2473>

